AIP Singapore AIP SUP 072/2021-1 19 MAY 2021

Contact

Post:

REPUBLIC OF SINGAPORE AERONAUTICAL INFORMATION SERVICES CIVIL AVIATION AUTHORITY OF SINGAPORE SINGAPORE CHANGI AIRPORT P.O. BOX 1, SINGAPORE 918141

Tel: (65) 6422 7036 AFS: WSSSYNYX Fax: (65) 64410221

Email: caas singaporeais@caas.gov.sg

URL: www.caas.gov.sg
URL: https://aim-sg.caas.gov.sg

AIP Supplement for Singapore



AIP SUP 072/2021 Effective from 25 MAY 2021 / 29 NOV 2021 Published on 19 MAY 2021

SINGAPORE CHANGI AIRPORT – CLOSURE OF AIRCRAFT STAND F34 AT TERMINAL 2

1 INTRODUCTION

1.1 This AIP Supplement is to inform airline operators and pilots of the closure of aircraft stand F34 at Terminal 2 in Singapore Changi Airport, from 0100UTC 25 MAY 2021 to 2200UTC 29 NOV 2021 to facilitate upcoming construction work activities.

2 CLOSURE OF AIRCRAFT STAND F34

2.1 Please refer to Appendix A for the enlarged location plan of the aircraft stand F34 at Terminal 2.

3 TEMPORARY CHANGES TO GROUND MARKINGS AND LIGHTING

- 3.1 Lead-in lines for aircraft stand F34 will be removed.
- 3.2 Marker boards with red fixed obstruction lighting will be placed across the Apron Boundary Line between the aircraft stand and taxilane R3.

4 CONCLUSION

- 4.1 This AIP Supplement supersedes AIP Supplement 060/2021 dated 22 April 2021.
- 4.2 Any change to the contents of this AIP Supplement will be notified through NOTAM.



ENLARGED LOCATION PLAN OF AIRCRAFT STAND F34 AT TERMINAL 2, SINGAPORE CHANGI AIRPORT



