

NOTICE OF AMENDMENT

Revision to AC 139-4-5 on Guidance on Development Works and Modification at the Aerodrome and AC 139-2-1 on Guidance on Aerodrome Manual or Heliport Manual

Please be informed that Advisory Circulars AC 139-4-5 on Guidance on Development Works and Modification at the Aerodrome and AC 139-2-1 on Guidance on Aerodrome Manual or Heliport Manual have been revised.

Revision 1 to AC 139-4-5 adds guidance on the use of unserviceability signs to mark areas affected by development works and introduces Form C2 for capturing outcomes of independent checks after completion of development works.

Revision 1 to AC 139-2-1 clarifies that implementation status for recommended practices in AC 139-4-2 (for aerodromes) and AC 139-4-6 (for heliports) should be included in the respective manuals.

The revised Advisory Circulars are effective from 23 January 2026 and can be found at our [CAAS website](https://www.caas.gov.sg).

Should you have any suggestions or comments on the above, please provide your feedback to <https://go.gov.sg/feedback-publication>.

Issued by
SAFETY POLICY AND PLANNING DIVISION
CIVIL AVIATION AUTHORITY OF SINGAPORE