

Contact

Post:

REPUBLIC OF SINGAPORE
AERONAUTICAL
INFORMATION SERVICES
CIVIL AVIATION AUTHORITY
OF SINGAPORE
SINGAPORE CHANGI
AIRPORT
P.O. BOX 1, SINGAPORE
918141

Tel: (65) 6595 6051

AFS: WSSSYNYX

Fax: (65) 64410221

Email: caas_singaporeais@caas.gov.sgURL: www.caas.gov.sgURL: <https://fpl-1.caasaim.gov.sg>**AIP Supplement for
Singapore****AIP SUP
089/2017****Effective from 04 SEP 2017****UFN****Published on 08 AUG 2017****SELETAR AIRPORT – COMMISSIONING OF RUNWAY GUARD LIGHTS****1 INTRODUCTION**

1.1 This AIP Supplement is to inform airline operators and pilots of the commissioning of the runway guard lights at Seletar Airport with effect from 04 September 2017 0500UTC.

2 LOCATION OF RUNWAY GUARD LIGHTS

2.1 Two pairs of unidirectional flashing yellow runway guard lights have been installed at each of the taxiway / runway intersections on Taxiways W1, W2, W3, E1, E2, E3 and E4.

2.2 Please see Appendix 1 for the locations of the runway guard lights.

3 CONCLUSION

3.1 Any change to the contents of this AIP Supplement will be notified through NOTAM.

3.2 This AIP Supplement will be cancelled once its contents is incorporated into AIP Singapore.

PAGE INTENTIONALLY LEFT BLANK

PAGE INTENTIONALLY LEFT BLANK