

Telephone: (65) 6595 6051
AFS: WSSSYNYX
Facsimile: (65) 6441 0221
caas_singaporeais@caas.gov.sg
www.caas.gov.sg

REPUBLIC OF SINGAPORE
AERONAUTICAL INFORMATION SERVICES
CIVIL AVIATION AUTHORITY OF SINGAPORE
SINGAPORE CHANGI AIRPORT
P.O. BOX 1, SINGAPORE 918141

**REVISIONS TO SINGAPORE CHANGI AIRPORT RUNWAY 02C/20C CLEARWAY
DIMENSION AND TAKE-OFF DISTANCE AVAILABLE (TODA)
WITH EFFECT FROM 17 SEPTEMBER 2015 0000UTC**

1 INTRODUCTION

- 1.1 Singapore Changi Airport is currently undergoing an upgrading programme which includes ground improvement and taxiway construction works. Part of the works to facilitate this programme is the shortening of the clearway for Runway 02C/20C from its current 270m to 60m.
- 1.2 The purpose of this AIP Supplement is to provide details on the revisions to Singapore Changi Airport Runway 02C/20C clearway dimension and TODA which shall be effective from **0000UTC, 17 September 2015**.

2 REVISED CLEARWAY DIMENSION AND TODA FOR RUNWAY 02C/20C

- 2.1 The clearway dimension for Runway 02C/20C (refer to AIP Singapore page WSSS AD 2-12 section WSSS AD 2.12 column 9) will be revised:

Runway	Clearway Dimension (m)
20C	60 X 150
02C	60 X 150

- 2.2 The TODA for Runway 02C/20C (refer to AIP Singapore page WSSS AD 2-13 section WSSS AD 2.13 column 4) will be revised:

Runway	Intersection Departures	TODA (m)
20C	Not applicable	4060
	E2	3910
	E3	3485
	E4	2810
	E5	2310

Runway	Intersection Departures	TODA (m)
02C	Not applicable	4060
	E10	3910
	E9	3405
	E8	3265
	E7	2615
	E6	2165

3 CANCELLATION

- 3.1 This AIP Supplement 136/15 will remain current until the information is incorporated into AIP Singapore.