Contact

Post:

REPUBLIC OF SINGAPORE AERONAUTICAL INFORMATION SERVICES CIVIL AVIATION AUTHORITY OF SINGAPORE SINGAPORE CHANGI AIRPORT P.O. BOX 1, SINGAPORE 918141

Tel: (65) 6595 6051 AFS: WSSSYNYX Fax: (65) 64410221

Email: caas singaporeais@caas.gov.sg

URL: www.caas.gov.sg

URL: https://fpl-1.caasaim.gov.sg

AIP Supplement for Singapore



AIP SUP
048/2016
Effective from 14 JUL 2016
UFN
Published on 30 JUN 2016

SELETAR AIRPORT - OPENING OF NEW AIRCRAFT STANDS D50, D51, D52, D53 AND D54, TAXIWAY EN, GROUND RUN-UP ENCLOSURE AND AIRCRAFT FIRE TRAINING GROUND AT NORTHEAST APRON, AND EXTENSION OF RUNWAY 21 RUNWAY END SAFETY AREA (RESA)

1 INTRODUCTION

- 1.1 This AIP Supplement is to inform ground handlers and pilots of the opening of new aircraft stands D50, D51, D52, D53 and D54; Taxiway EN; ground run-up enclosure and aircraft fire training ground at Northeast Apron; and the extension of RESA at Runway 21 with effect from 0000UTC 14 July 2016.
- 1.2 This AIP Supplement also describes the procedure for towing aircraft from the new aircraft stands D50, D51, D52, D53 and D54.

2 NEW AIRCRAFT STANDS, TAXIWAY, GROUND RUN-UP ENCLOSURE, AIRCRAFT FIRE TRAINING GROUND AND EXTENDED RESA AT RUNWAY 21

2.1 Aircraft stands D50, D51, D52, D53 and D54 will be used for tow operations only. Please see Annex A for details on the new aircraft stands and Appendices 1A, 2A and 3A for the locations of aircraft stands D50, D51, D52, D53 and D54; Taxiway EN; ground run-up enclosure; aircraft fire training ground and the extended RESA at Runway 21.

3 PROCEDURE FOR TOWING AIRCRAFT

3.1 Please refer to Annex B for the procedure for towing aircraft from the new aircraft stands D50, D51, D52, D53 and D54.

4 CONCLUSION

- 4.1 Any change to the contents of this AIP Supplement will be notified through NOTAM.
- 4.2 This AIP Supplement will be cancelled once its contents are incorporated into AIP Singapore.



DETAILS OF NEW AIRCRAFT STANDS D50, D51, D52, D53 AND D54

Aircraft Stand			Aircraft types that can be	
Number	Location (WGS-84 coordinates)	Elevation	parked at the aircraft stand	
D50	01 25 00.056N 103 52 11.563E	6.680m (21.916ft)	A319, A320, A321, AT45, AT46, AT75, AT76, B737, B752, FA7X, FK50, FK70, F100, DH8D (including aircraft types with wingspan not exceeding 40m and length not exceeding 47m)	
D51	01 25 01.585N 103 52 12.561E	6.440m (21.129ft)	A319, A320, A321, AT45, AT46, AT75, AT76, B737, B752, FA7X, FK50, FK70, F100, DH8D (including aircraft types with wingspan not exceeding 38m and length not exceeding 47m)	
D52	01 25 02.828N 103 52 13.373E	6.280m (20.604ft)	A319, A320, A321, AT45, AT46, AT75, AT76, B737, B752, FA7X, FK50, FK70, F100, DH8D (including aircraft types with wingspan not exceeding 38m and length not exceeding 47m)	
D53	01 25 04.357N 103 52 14.372E	6.040m (19.816ft)	A319, A320, A321, AT45, AT46, AT75, AT76, B737, B752, FA7X, FK50, FK70, F100, DH8D (including aircraft types with wingspan not exceeding 38m and length not exceeding 47m)	
D54	01 25 05.600N 103 52 15.184E	5.820m (19.094ft)	A319, A320, A321, AT45, AT46, AT75, AT76, B737, B752, FA7X, FK50, FK70, F100, DH8D (including aircraft types with wingspan not exceeding 38m and length not exceeding 47m)	




ANNEX B

PROCEDURE FOR TOWING AIRCRAFT FROM AIRCRAFT STANDS D50, D51, D52, D53 AND D54				
Aircraft stand	Pushback / Tow Forward Procedure	Phraseology used by SELETAR GROUND		
D50, D51, D52, D53, D54	The tow crew shall request from Seletar Ground (vehicular) on 122.9MHz for pushback approval. Upon receiving the approval, the aircraft shall be pushed back onto TWY EN to face South until its nosewheel is at the intersection of the aircraft stand pushback line and TWY EN centreline. The aircraft shall then be towed from there.	Pushback approved to face South		




LOCATION PLAN OF AIRCRAFT STANDS D50, D51, D52, D53 AND D54, TAXIWAY EN, GROUND RUN-UP ENCLOSURE, AIRCRAFT FIRE TRAINING GROUND AT NORTHEAST APRON AND EXTENDED RESA AT RUNWAY 21 (WITH EFFECT FROM 0000UTC 14 JULY 2016)



PAGE INTENTIONALLY LEFT BLANK

ENLARGED LOCATION PLAN OF AIRCRAFT STANDS D50, D51, D52, D53 AND D54 AND TAXIWAY EN WITH AIRFIELD LIGHTINGS (WITH EFFECT FROM 0000UTC 14 JULY 2016)

APPENDIX 2A







Taxiway reflective marker light

PAGE INTENTIONALLY LEFT BLANK

APPENDIX 3A

ENLARGED LOCATION PLAN OF GROUND RUN-UP ENCLOSURE WITH AIRFIELD LIGHTINGS (WITH EFFECT FROM 0000UTC 14 JULY 2016)







Taxiway reflective marker light

PAGE INTENTIONALLY LEFT BLANK