

Contact

Post:

REPUBLIC OF SINGAPORE
AERONAUTICAL
INFORMATION SERVICES
CIVIL AVIATION AUTHORITY
OF SINGAPORE
SINGAPORE CHANGI
AIRPORT
P.O. BOX 1, SINGAPORE
918141

Tel: (65) 6422 7036

AFS: WSSSYNYX

Fax: (65) 64410221

Email: caas_singaporeais@caas.gov.sgURL: www.caas.gov.sgURL: <https://aim-sg.caas.gov.sg>**AIP Supplement for
Singapore****AIP SUP****026/2020****Effective from 29 MAR 2020****/ 24 OCT 2020****Published on 20 MAR 2020****SINGAPORE CHANGI AIRPORT - WORKS SCHEDULE AND MOVEMENT AREA
RESTRICTIONS PERTAINING TO CHANGI EAST DEVELOPMENT WORKS****1 INTRODUCTION**

1.1 This AIP Supplement is to update the aviation industry of the works schedule and movement areas restrictions at Singapore Changi Airport with effect from 29 March 2020 1630UTC to 24 October 2020 2200UTC due to the on-going upgrading programme of Changi East Development Works.

2 CONSTRUCTION ZONES FOR CHANGI EAST DEVELOPMENT WORKS

2.1 Please refer to **Appendix A** for the location of the construction work zones.

3 LONG CLOSURES OF RUNWAY 02L/20R AND RUNWAY 02C/20C

3.1 Runway 02L/20R and Runway 02C/20C will be closed between 1630UTC and 2200UTC nightly from 29 March 2020 to 24 October 2020 for works and maintenance on the dates indicated in columns (b) and (c) respectively. Runway 02L/20R and Runway 02C/20C will remain operational between 1630UTC and 2200UTC on the dates indicated in column (d):

Month (a)	Runway 02L/20R closed (b)	Runway 02C/20C closed (c)	Runways 02L/20R and 02C/20C operational (d)
March 2020	30 and 31	29	-
April 2020	2, 6, 7, 9, 13, 14, 16, 20, 21, 23, 27, 28 and 30	1, 5, 8, 12, 15, 19, 22, 26 and 29	3, 4, 10, 11, 17, 18, 24 and 25
May 2020	4, 5, 7, 11, 12, 14, 18, 19, 21, 25, 26 and 28	3, 6, 10, 13, 17, 20, 24, 27 and 31	1, 2, 8, 9, 15, 16, 22, 23, 29 and 30
June 2020	1, 2, 4, 8, 9, 11, 15, 16, 18, 22, 23, 25, 29 and 30	3, 7, 10, 14, 17, 21, 24 and 28	5, 6, 12, 13, 19, 20, 26 and 27
July 2020	2, 6, 7, 9, 13, 14, 16, 20, 21, 23, 27, 28 and 30	1, 5, 8, 12, 15, 19, 22, 26 and 29	3, 4, 10, 11, 17, 18, 24, 25 and 31
August 2020	3, 4, 6, 10, 11, 13, 17, 18, 20, 24, 25, 27 and 31	2, 5, 9, 12, 16, 19, 23, 26 and 30	1, 7, 8, 14, 15, 21, 22, 28 and 29
September 2020	1, 3, 7, 8, 10, 14, 15, 17, 21, 22, 24, 28 and 29	2, 6, 9, 13, 16, 20, 23, 27 and 30	4, 5, 11, 12, 18, 19, 25 and 26
October 2020	1, 5, 6, 8, 12, 13, 15, 19, 20 and 22	4, 7, 11, 14, 18 and 21	2, 3, 9, 10, 16, 17, 23 and 24

3.2 For Runway 02C/20C closure from 1630UTC to 2200UTC, Taxiway EP between Taxiway L9 and Taxiway E11 will also be closed due to work in progress.

3.3 Scheduled closure timings for Runway 02L/20R and Runway 02C/20C stipulated in the AIP Singapore, section WSSS AD 2.12. item 12, paragraphs 1a) and 2a) is hereby superseded for the duration of this AIP Supplement.

4 SHORT CLOSURES OF RUNWAY 02L/20R and RUNWAY 02C/20C

4.1 Depending on which runway is closed or if both runways remain operational, the runway maintenance closures will be conducted as follows:

- a. Before the closure of Runway 02L/20R between 1630UTC and 2200UTC, a 10 minutes maintenance closure will be conducted on Runway 02C/20C between 1605UTC and 1615UTC, and vice versa.
- b. When the closed Runway 02L/20R or Runway 02C/20C is reopen at 2200UTC, short maintenance closure of 5 minutes scheduled to be conducted daily between 2300-2305UTC and 2320-2325UTC on Runway 02L/20R and Runway 02C/20C respectively (refer to AIP Singapore section WSSS AD 2.12 item 12, paragraphs 1b) and 2b)) will be cancelled. Instead, after the reopening of closed Runway 02L/20R or closed Runway 02C/20C at 2200UTC, a 15 minutes maintenance closure will be conducted on the other runway, i.e. Runway 02C/20C between 2315UTC and 2330UTC or Runway 02L/20R between 2300UTC and 2315UTC respectively.
- c. If both runways remain operational, 30 minutes maintenance closure will be conducted between 1830-1900UTC and 1930-2000UTC on Runway 02L/20R and Runway 02C/20C respectively.
- d. The table below shows the details and the maintenance closure timings depending on which runway is closed or when both runways remain operational.

Scenario	AIP Singapore WSSS AD 2.12 item 12	Addition of 15 minutes RWY maintenance closure	Addition of 10 or 30 minutes RWY maintenance closure
	Cancellation of 5 minutes RWY maintenance closure		
RWY 02L/20R closed 1630-2200UTC	RWY 02L/20R 2300-2305UTC	RWY 02C/20C 2315-2330UTC	RWY 02C/20C 1605-1615UTC
RWY 02C/20C closed 1630-2200UTC	RWY 02C/20C 2320-2325UTC	RWY 02L/20R 2300-2315UTC	RWY 02L/20R 1605-1615UTC
RWY 02L/20R and RWY 02C/20C remain operational 1630-2200UTC	Not applicable	Not applicable	RWY 02L/20R 1830-1900UTC RWY 02C/20C 1930-2000UTC

5 MARKING AND LIGHTING

5.1 All unserviceable areas on taxiways or aprons will be demarcated by marker boards. The marker boards will be painted in alternate bands of red and white, and will be lighted at night and during limited visibility conditions by omni-directional fixed red lights.

5.2 All unserviceable areas 105m from Runway 02C/20C centreline will be demarcated by marker boards placed parallel to Runway 02C/20C. The marker boards will be painted in alternate bands of red and white.

6 PRECAUTIONS

6.1 During the construction period, pilots are to take note of the following at the work areas as shown in **Appendix A**:


- a. Presence of construction equipment beyond 105m from Runway 02C/20C centreline and on the northern and southern ends of Runway 02C/20C threshold.
- b. All construction equipment will be kept clear of the obstacle free zone when Runway 02C/20C is operational.
- c. Emergency response and evacuation plan (for removal of machinery and manpower) will be in place in case of any airport emergency.
- d. Runway 02C/20C will be closed between 1630UTC and 2200UTC on the dates specified in paragraph 3.1. All aircraft operators operating during these periods are to plan to carry sufficient contingency fuel as only one runway will be available.

7 CHANGES

7.1 Any changes to the contents of this AIP Supplement will be notified through NOTAM.

Location of the construction work zones [Appendix A](#)

Changi East Work Location



PAGE INTENTIONALLY LEFT BLANK